

HS Marston Aerospace Limited

Document Number: ME899	Sheet 1 of 13	Date ©: 23.3.10	Issue: 23
-------------------------------	-----------------------------	------------------------	------------------

2 CAPABILITY SCHEDULE - HTG

	<u>Original Manufacturer</u>	<u>Part No</u>	<u>Repair Scheme</u>	<u>EASA Form 1</u>	<u>FAA FORM 8130-3</u>
2.1	Hamilton Sundstrand	719235-4	21-51-02	✓	✓
2.2	Hamilton Sundstrand	719235-5	21-51-02	✓	✓
2.3	Hamilton Sundstrand	719235-6	21-51-02	✓	✓
2.4	Hamilton Sundstrand	719235-7	21-51-02	✓	✓
2.5	Hamilton Sundstrand	719235-8	21-51-02	✓	✓
2.6	Hamilton Sundstrand	719235-9	21-51-02	✓	✓
2.7	Hamilton Sundstrand	719235-4	ME242/19235	✓	✓
2.8	Hamilton Sundstrand	719235-5	ME242/19235	✓	✓
2.9	Hamilton Sundstrand	719235-6	ME242/19235	✓	✓
2.10	Hamilton Sundstrand	719235-7	ME242/19235	✓	✓
2.11	Hamilton Sundstrand	719235-8	ME242/19235	✓	✓
2.12	Hamilton Sundstrand	719235-9	ME242/19235	✓	✓
2.13	Hamilton Sundstrand	733949-5	21-51-14	✓	✓
2.14	Hamilton Sundstrand	733949-6	21-51-14	✓	✓
2.15	Hamilton Sundstrand	733949-7	21-51-14	✓	✓
2.16	Hamilton Sundstrand	733949-8	21-51-14	✓	✓
2.17	Hamilton Sundstrand	767115-1	21-51-14	✓	✓
2.18	Hamilton Sundstrand	767115-2	21-51-14	✓	✓
2.19	Ametek Hughes Treitler	12325-000	79-21-02	✓	✓
2.20	Ametek Hughes Treitler	13325-000	79-21-02	✓	✓
2.21	Ametek Hughes Treitler	2-303-491-01	79-21-02	✓	✓
2.22	Ametek Hughes Treitler	2-303-491-02	79-21-02	✓	✓
2.23	Ametek Hughes Treitler	11698-000	24-11-01	✓	✓

HS Marston Aerospace Limited

Document Number: ME899	Sheet 2 of 13	Date ©: 23.3.10	Issue: 23
-------------------------------	----------------------	------------------------	------------------

	<u>Original Manufacturer</u>	<u>Part No</u>	<u>Repair Scheme</u>	<u>EASA Form 1</u>	<u>FAA FORM 8130-3</u>
2.24	Ametek Hughes Treitler	12698-000	24-11-01	✓	✓
2.25	Ametek Hughes Treitler	11622-000	79-21-20	✓	✓
2.26	Ametek Hughes Treitler	12622-000	79-21-20	✓	✓
2.27	Ametek Hughes Treitler	13622-000	79-21-20	✓	✓
2.28	Ametek Hughes Treitler	15622-000	79-21-20	✓	✓
2.29	HS Marston Aerospace	D1150-10A	24-23-01	✓	✓
2.30	HS Marston Aerospace	D1151-10A	29-20-01	✓	✓
2.31	HS Marston Aerospace	D1443-100A	79-21-11	✓	✓
2.32	HS Marston Aerospace	D1688-200A	79-21-31	✓	✓
2.33	HS Marston Aerospace	D1719-200A	73-10-01	✓	✓
2.34	HS Marston Aerospace	D1719-300A	63-10-01	✓	✓
2.35	HS Marston Aerospace	D1719-400A	63-10-01	✓	✓
2.36	HS Marston Aerospace	D1719-500A	63-10-01	✓	✓
2.37	HS Marston Aerospace	D1834-10A	79-21-21	✓	✓
2.38	HS Marston Aerospace	D1834-100A	79-21-21	✓	✓
2.39	HS Marston Aerospace	D1979-200A	49-90-01	✓	✓
2.40	HS Marston Aerospace	D2310-10A	79-21-41	✓	✓
2.41	HS Marston Aerospace	D2346-10A	49-91-01	✓	✓
2.42	HS Marston Aerospace	D291-2A	28-4-1	✓	✓
2.43	HS Marston Aerospace	D291-8A	28-5-1	✓	✓
2.44	HS Marston Aerospace	D291-52A	28-5-1	✓	✓
2.45	HS Marston Aerospace	D291-53A	28-6-1	✓	✓
2.46	HS Marston Aerospace	D291-85A	28-3-1	✓	✓
2.47	HS Marston Aerospace	D3292-1600A	24-10-53	✓	✓

HS Marston Aerospace Limited

Document Number: ME899	Sheet 3 of 13	Date ©: 23.3.10	Issue: 23
-------------------------------	----------------------	------------------------	------------------

	<u>Original Manufacturer</u>	<u>Part No</u>	<u>Repair Scheme</u>	<u>EASA Form 1</u>	<u>FAA FORM 8130-3</u>
2.48	HS Marston Aerospace	D3292-1700A	24-10-53	✓	✓
2.49	HS Marston Aerospace	D3292-1800A	24-10-53	✓	✓
2.50	HS Marston Aerospace	D3292-3000A	75-21-01	✓	✓
2.51	HS Marston Aerospace	D3292-4000A	75-21-01	✓	✓
2.52	HS Marston Aerospace	D3439-1300A	79-20-05	✓	✓
2.53	HS Marston Aerospace	D2552-600B-01	73-10-05	✓	✓
2.54	HS Marston Aerospace	D2552-600B-02	73-10-05	✓	✓
2.55	HS Marston Aerospace	D1508-120A	73-11-12	✓	✓
2.56	HS Marston Aerospace	D1573-10A	73-15-05	✓	✓
2.57	HS Marston Aerospace	D1569-64A	73-11-3	✓	✓
2.58	HS Marston Aerospace	D1569-80A	73-11-3	✓	✓
2.59	HS Marston Aerospace	D1569-120A	73-11-3	✓	✓
2.60	HS Marston Aerospace	D1876-1000A	75-22-41	✓	✓
2.61	HS Marston Aerospace	D2041-1000A	36-10-05	✓	✓
2.62	HS Marston Aerospace	D2045-300A	49-90-02	✓	✓
2.63	HS Marston Aerospace	D2228-250A	73-10-1	✓	✓
2.64	HS Marston Aerospace	D2397-10A	79-10-01	✓	✓
2.65	HS Marston Aerospace	D3047-270A	36-10-2	✓	✓
2.66	HS Marston Aerospace	D3047-271A	36-10-2	✓	✓
2.67	HS Marston Aerospace	D3047-280A	36-10-2	✓	✓
2.68	HS Marston Aerospace	D3047-281A	36-10-2	✓	✓
2.69	HS Marston Aerospace	D3047-700A	36-10-2	✓	✓
2.70	HS Marston Aerospace	D3047-701A	36-10-2	✓	✓
2.71	HS Marston Aerospace	D3117-1A	36-10-3	✓	✓

HS Marston Aerospace Limited

Document Number: ME899	Sheet 4 of 13	Date ©: 23.3.10	Issue: 23
-------------------------------	-----------------------------	------------------------	------------------

	<u>Original Manufacturer</u>	<u>Part No</u>	<u>Repair Scheme</u>	<u>EASA Form 1</u>	<u>FAA FORM 8130-3</u>
2.72	HS Marston Aerospace	D3117-2A	36-10-3	✓	✓
2.73	HS Marston Aerospace	D3117-601A	36-10-3	✓	✓
2.74	HS Marston Aerospace	D3117-602A	36-10-3	✓	✓
2.75	HS Marston Aerospace	D3117-651A	36-10-3	✓	✓
2.76	HS Marston Aerospace	D3117-652A	36-10-3	✓	✓
2.77	HS Marston Aerospace	D3117-691A	36-10-3	✓	✓
2.78	HS Marston Aerospace	D3117-692A	36-10-3	✓	✓
2.79	HS Marston Aerospace	D2022-100A	ME242/D2022	✓	✓
2.80	HS Marston Aerospace	D2022-140A	ME242/D2022	✓	✓
2.81	HS Marston Aerospace	D2024-100A	ME242/D2024	✓	✓
2.82	HS Marston Aerospace	D2024-140A	ME242/D2024	✓	✓
2.83	Secan	11-82941-M2	TS2024-5	✓	✓
2.84	Secan	11-8291-M3	TS2022-5	✓	✓
2.85	Sundstrand	723324(2-303-254-01)	79-21-01	✓	✓
2.86	Sundstrand	723324A(2-0303-254-02)	79-21-01	✓	✓
2.87	Sundstrand	723324B(2-303-254-03)	79-21-01	✓	✓
2.88	Sundstrand	723324C(2-303-254-05)	79-21-01	✓	✓
2.89	Sundstrand	723324D(2-303-254-06)	79-21-01	✓	✓
2.90	Ametek Hughes Treitler	14844-000	24-21-42	✓	✓
2.91	Ametek Hughes Treitler	15844-000	24-21-42	✓	✓
2.92	Ametek Hughes Treitler	16844-000	24-21-42	✓	✓
2.93	Ametek Hughes Treitler	60141-000	24-21-32	✓	✓
2.94	Ametek Hughes Treitler	60010-000	24-10-14	✓	✓
2.95	Ametek Hughes Treitler	70010-000	24-10-14	✓	✓

HS Marston Aerospace Limited

Document Number: ME899	Sheet 5 of 13	Date ©: 23.3.10	Issue: 23
-------------------------------	-----------------------------	------------------------	------------------

	<u>Original Manufacturer</u>	<u>Part No</u>	<u>Repair Scheme</u>	<u>EASA Form 1</u>	<u>FAA FORM 8130-3</u>
2.96	Ametek Hughes Treitler	80010-000	24-10-14	✓	✓
2.97	Hamilton Sundstrand	810210-1	21-72-02	✓	✓
2.98	Hamilton Sundstrand	810210-2	21-72-02	✓	✓
2.99	Hamilton Sundstrand	810208-1	21-52-02	✓	✓
2.100	Hamilton Sundstrand	810208-2	21-52-02	✓	✓
2.101	Hamilton Sundstrand	810208-4	21-52-02	✓	✓
2.102	Hamilton Sundstrand	810208-5	21-52-02	✓	✓
2.104	Hamilton Sundstrand	810208-6	21-52-02	✓	✓
2.105	Hamilton Sundstrand	810208-7	21-52-02	✓	✓
2.106	Hamilton Sundstrand	810208-9	21-52-02	✓	✓
2.107	Hamilton Sundstrand	810208-102	21-52-02	✓	✓
2.108	Hamilton Sundstrand	810208-104	21-52-02	✓	✓
2.109	Hamilton Sundstrand	810208-105	21-52-02	✓	✓
2.110	Hamilton Sundstrand	810208-114	21-52-02	✓	✓
2.111	Hamilton Sundstrand	810208-115	21-52-02	✓	✓
2.112	Hamilton Sundstrand	810208-117	21-52-02	✓	✓
2.113	Ametek Hughes Treitler	11553-000	11553-00	✓	✓
2.114	Ametek Hughes Treitler	12553-000	11553-00	✓	✓
2.115	Hamilton Sundstrand	815950-1	39-12-17	✓	✓
2.116	HS Marston Aerospace	163521538	FRS 6887	✓	✓
2.117	HS Marston Aerospace	D2887-615A	79-21-61	✓	✓
2.118	HS Marston Aerospace	D2887-715A	79-21-61	✓	✓
2.119	HS Marston Aerospace	D2887-815A	79-21-61	✓	✓
2.120	HS Marston Aerospace	D2967-100A	73-10-15	✓	✓

HS Marston Aerospace Limited

Document Number: ME899	Sheet 6 of 13	Date ©: 23.3.10	Issue: 23
-------------------------------	-----------------------------	------------------------	------------------

	<u>Original Manufacturer</u>	<u>Part No</u>	<u>Repair Scheme</u>	<u>EASA Form 1</u>	<u>FAA FORM 8130-3</u>
2.121	HS Marston Aerospace	D2967-200A	73-10-15	✓	✓
2.122	HS Marston Aerospace	D6031-200A	73-10-20	✓	✓
2.123	HS Marston Aerospace	D6031-300A	73-10-20	✓	✓
2.124	HS Marston Aerospace	D6031-400A	73-10-20	✓	✓
2.125	HS Marston Aerospace	D6031-500A	73-10-20	✓	✓
2.126	HS Marston Aerospace	D6031-600A	73-10-20	✓	✓
2.127	HS Marston Aerospace	D6031-700A	73-10-20	✓	✓
2.128	HS Marston Aerospace	D2351-100A	73-10-10	✓	✓
2.129	HS Marston Aerospace	D2351-200A	73-10-10	✓	✓
2.130	Hamilton Sundstrand	820905-1	21-53-04	✓	✓
2.131	Hamilton Sundstrand	820905-2	21-53-04	✓	✓
2.132	Hamilton Sundstrand	820905-3	21-53-04	✓	✓
2.133	Hamilton Sundstrand	4950242	49-91-03	✓	✓
2.134	Hamilton Sundstrand	4950862	49-91-03	✓	✓
2.135	Hamilton Sundstrand	4950882	49-91-03	✓	✓
2.136	Hamilton Sundstrand	4951093	49-91-03	✓	✓
2.137	Hamilton Sundstrand	M4950242	49-91-03	✓	✓
2.138	Hamilton Sundstrand	M4950862	49-91-03	✓	✓
2.139	Hamilton Sundstrand	M4951093	49-91-03	✓	✓
2.140	HS Marston Aerospace	D6397-10A	36-30-00	✓	✓
2.141	HS Marston Aerospace	HEA3610E161-501	30-11-04	✓	✓
2.142	HS Marston Aerospace	HEA3610E163-501	30-11-04	✓	✓
2.143	HS Marston Aerospace	HEA3610E181-503	30-11-04	✓	✓
2.144	HS Marston Aerospace	HEA3610E183-503	30-11-04	✓	✓

HS Marston Aerospace Limited

Document Number: ME899	Sheet 7 of 13	Date ©: 23.3.10	Issue: 23
-------------------------------	-----------------------------	------------------------	------------------

	<u>Original Manufacturer</u>	<u>Part No</u>	<u>Repair Scheme</u>	<u>EASA Form 1</u>	<u>FAA FORM 8130-3</u>
2.145	HS Marston Aerospace	HEA3610E186-501		✓	✓
2.146	HS Marston Aerospace	HEA3610E187-501		✓	✓
2.147	HS Marston Aerospace	HEA3610E180-501		✓	✓
2.148	HS Marston Aerospace	HEA3610E182-501		✓	✓
2.149	HS Marston Aerospace	D6557-10A	79-21-42	✓	✓
2.150	HS Marston Aerospace	D6557-100A	79-21-42	✓	✓
2.151	HS Marston Aerospace	D6557-200A	79-21-42	✓	✓
2.152	HS Marston Aerospace	D6557-300A	79-21-42	✓	✓
2.153	HS Marston Aerospace	D6557-400A	79-21-42	✓	✓
2.154	HS Marston Aerospace	D6514-10A	24-21-41	✓	✓
2.155	HS Marston Aerospace	D6514-100A	24-21-41	✓	✓
2.156	HS Marston Aerospace	D6514-200A	24-21-41	✓	✓
2.157	HS Marston Aerospace	D6514-300A	24-21-41	✓	✓
2.158	HS Marston Aerospace	D6514-400A	24-21-41	✓	✓
2.159	Sumitomo Precision Products Ltd.	50026001-1	CMM 79-21-42	✓	✓
2.160	Sumitomo Precision Products Ltd.	OA2730-001	CMM 79-21-42	✓	✓
2.161	Sumitomo Precision Products Ltd.	50034001-1	CMM 79-28-03	✓	✓
2.162	Sumitomo Precision Products Ltd.	OA3150-001	CMM 79-28-03	✓	✓
2.163	Sumitomo Precision Products Ltd.	OF25-001	CMM 79-21-43	✓	✓
2.164	Sumitomo Precision Products Ltd.	OF25-101	CMM 79-21-43	✓	✓
2.165	Sumitomo Precision Products Ltd.	OF25-201	CMM 79-21-43	✓	✓
2.166	Sumitomo Precision Products Ltd.	OF25-301	CMM 79-21-43	✓	✓
2.167	Sumitomo Precision Products Ltd.	OF25-401	CMM 79-21-43	✓	✓
2.168	Sumitomo Precision Products Ltd.	OF32-001	CMM 79-21-43	✓	✓

HS Marston Aerospace Limited

Document Number: ME899	Sheet 8 of 13	Date ©: 23.3.10	Issue: 23
-------------------------------	----------------------	------------------------	------------------

	<u>Original Manufacturer</u>	<u>Part No</u>	<u>Repair Scheme</u>	<u>EASA Form 1</u>	<u>FAA FORM 8130-3</u>
2.169	Sumitomo Precision Products Ltd.	OF32-101	CMM 79-21-43	✓	✓
2.170	Sumitomo Precision Products Ltd.	OF33-001	CMM 79-21-43	✓	✓
2.171	Sumitomo Precision Products Ltd.	55022001-1	CMM 79-21-43	✓	✓
2.172	Sumitomo Precision Products Ltd.	55022001-11	CMM 79-21-43	✓	✓
2.173	Sumitomo Precision Products Ltd.	55025001-01	CMM 79-21-43	✓	✓
2.174	Sumitomo Precision Products Ltd.	55030001-11	CMM 79-21-43	✓	✓
2.175	HS Marston Aerospace Ltd	D1876-5000A	CMM 75-22-41	✓	✓
2.176	HS Marston Aerospace Ltd	D2887-355C	CMM 79-21-61	✓	✓
2.177	HS Marston Aerospace Ltd	D6599-1000A (157666-1)	CMM 21-50-01	✓	✓
2.178	HS Marston Aerospace Ltd	7010106 (D7026-300A)	CMM 21-73-06	✓	✓
2.179	HS Marston Aerospace Ltd	7011041 (H2013-10)	CMM 21-52-78	✓	✓
2.180	HS Marston Aerospace Ltd	7-011043 (H2014-10)	CMM 21-52-78	✓	✓
2.181	Hamilton Sundstrand	753355-4	CMM 21-51-63	✓	✓
2.182	Hamilton Sundstrand	753355-8	CMM 21-51-63	✓	✓
2.183	Hamilton Sundstrand	753355-9	CMM 21-51-63	✓	✓
2.184	Hamilton Sundstrand	778683-2	CMM 21-51-50	✓	✓
2.185	Hamilton Sundstrand	778683-3	CMM 21-51-50	✓	✓
2.186	Hamilton Sundstrand	778683-4	CMM 21-51-50	✓	✓
2.187	Hamilton Sundstrand	778683-5	CMM 21-51-50	✓	✓

HS Marston Aerospace Limited

Document Number: ME899	Sheet 9 of 13	Date ©: 23.3.10	Issue: 23
-------------------------------	-----------------------------	------------------------	------------------

COPYRIGHT © HS MARSTON AEROSPACE LIMITED

This document contains confidential information which is the property of HS Marston Aerospace Limited. The document must NOT be copied nor its contents communicated to any person or company without authorisation in writing from HS Marston Aerospace Limited. Any authorised recipients may only use this document for the purpose for which it has been supplied. Copyright, patent, design right or any other intellectual property right relating to any features disclosed in the document vests exclusively with HS Marston Aerospace Limited.

The trademark Marston is used under licence from IMI Marston Limited.

COMPILED				AGREED				APPROVED			
SIG.		DEPT.		SIG.		DEPT.		SIG.		DEPT.	
D Allen		R&O		Kevin Dawson		R&O		R A Winstone		Quality	
ISSUE No:	DATE ©	19	FEB 08	20	AUG 08	21	MAR 09	22	MAY 09	23	MAR 10
AMENDMENT No:		MTL 6065		MTL 6236		MTL 6452		MTL 6564		MTL 6886	